


































Name	Description	Waste %	Qty	Units	Units	Cost Eacl	Markup %	Price Eacl	Price Totl	Color
 Carpet - SqYd To Demo		0	123.38	SQ YL		0	0	0	0	
 VCT to Demo		0	3.39	SQ YL		0	0	0	0	
 VCTin Utility rm to demo		0	6.17	SQ YL		0	0	0	0	
 Linear			0	FT		0	0	0	0	
 Office walls		20	2238.84	SQ FT		0	0	0	0	
 Utility room walls		20	207.79	SQ FT		0	0	0	0	
 30x68 doors		0	6	EA		0	0	0	0	
 2/0x6/8 DBL		0	1	EA		0	0	0	0	
 Interior Walls		20	128.06	SQ FT		0	0	0	0	
 Concrete Removal 2"		0	89.69	SQ FT		0	0	0	0	
 Infill wall at door		20	103.1	SQ FT		0	0	0	0	
 Concrete Slab - CuYd		10	0.25	CU YL		0	0	0	0	
 Base trim		20	228.53	FT		0	0	0	0	
 Chair Rail		20	146.1	FT		0	0	0	0	
 Demo existing wall		0	13.06	FT		0	0	0	0	
 Accoustical Ceiling - New tile		20	1360.4	SQ FT		0	0	0	0	
 Linear to SQ FT (walls) - Lead Lining		10	151.87	SQ FT		0	0	0	0	